November 7, 2011

State of Oregon
Building Codes Division
Better Buildings for Oregon

Errata for the 2010 Oregon Structural Specialty Code, first printing

~~Strikethrough~~ text represents deleted language

Underlined text represents added language

Page 28, Delete ORS 169.005(4), Replace with ORS 169.005(5):

304.2 Lockup facilities. Buildings containing lockup facilities, as defined in ~~ORS 169.005(4),~~ ORS 169.005(5), shall comply with the following provisions:

1. Areas containing lockup facilities shall be separated from other rooms, spaces or areas by an approved smoke barrier (see Section 909.5)

2. The smoke control zone in which the lockup cells are located shall be provided with an automatic fire sprinkler system complying with Chapter 9 requirements for Group I-3 occupancies.

3. The smoke control zone in which the lockup area is located shall be provided with an automatic smoke detection system installed in accordance with the Fire Code Group I-3 occupancies.

4. The combined occupant load of the holding cells shall not exceed five.

Note:
In addition the 2010 Oregon Structural Specialty Code as printed by the International Codes Council, incorporates the International Codes Council's errata for the first printing of the 2009 International Building Code.

Contact:
Richard Rogers, Structural Program Chief, 503-378-4472 or Richard.Rogers@state.or.us
Steve Judson, Structural Code Specialist, 503-378-4635 or Steven.W.Judson@state.or.us